## **HS-AS Studs**

adapters



Adapters to connect accelerometers to machine faces.

Mounting Studs provide a secure, permanent or semi-permanent point of connection

Part No.	Connection Point 1	Connection Point 2			
				90	
HS-AS006	Quick Fit Female	1/4"-28 UNF Male			
HS-AS009	M6 Female	M8 Male			
HS-AS026	10-32 UNF Male	M6 Male	(9)		
110-A0020	10-32 ONI Male	Wo Wale			
HS-AS028	Quick Fit Female ½" UNC	1/4"-28 UNF Male			
HS-AS030	M8 x 1.25 Female	1/8"BSPT Male			
HS-AS032	Quick Fit Female	M8 Male			
HS-AS039	Quick Fit Female ½" UNC	10-32 UNF Male		H	
ПО-АООЭЭ	Quick Fit Female 72 UNC	10-32 UNF Male			
HS-AS045	Quick Fit Female	M5 Female			
HS-AS088	Quick Fit Female 9/16" UNC	M5 Female		-	
HS-AS092	3/8" UNF Female	3/8" NPT Male			
110 40400	1/2 00 1115 5	1/2 NIDT M. I	3 <b>33</b> 64		
HS-AS103	1/4"-28 UNF Female	1/4" NPT Male			
HS-AS107-M6	M6 Female	M6 Male	3		
HS-AS111	M8 Female	M8 Female			
HS-AS119	1/4"-28 UNF Female	1/4"-28UNF Male			
HS-AS121	1/4"-28 UNF Female	3/8"-16 UNC Male	6		





