## HS-AS Studs Quick Fit threads



For use with accelerometers with quick-fit threads.

Mounting Studs provide a secure, permanent or semi-permanent point of connection

Part No.	Connection Point 1	Connection Point 2		
HS-AS001	Quick Fit Male	Glue Face		
HS-AS002	Quick Fit Male	M8 Male		
HS-AS003	Quick Fit Male	M6 Male		
HS-AS004	Quick Fit Male	1/4"-28 UNF Male		
				6
HS-AS007	Quick Fit Male	M10 Male		
				<u></u>
HS-AS010	Quick Fit Male	M8 x 1.25 Female		
HS-AS011	Quick Fit Male	M6 x 1 Female		
HS-AS012	Quick Fit Male	1/4"-28 UNF Female		
HS-AS013	Quick Fit Male (9/16" UNC)	Glue Face	1	
HS-AS018	Quick Fit Male (½" UNC)	Glue Face	3	







## HS-AS Studs Quick Fit threads

Part N	o. Connection I	Point 1 Connection	n Point 2	
HS-AS03	Quick Fit Male	M8 x 1 Male		
HS-AS03	Quick Fit Male (1/2	½" UNC) M6 x 1 Male		
				<u></u>
HS-AS03	Quick Fit Male (1	½" UNC) M8 x 1.25 Mal	e	
HS-AS04	Quick Fit Male	3/8" BSP		
HS-AS04	Quick Fit Male	1/8" BSP		
HS-AS06	Quick Fit Male	M5 Male		
HS-AS06	Quick Fit Male	Glue face and	M6 x 1 Female	
HS-AS07	2 Quick Fit Male	M8 x 8mm Ma	le	
HS-AS07	78 Quick Fit Male	Glue Face in 3	316L Stainless Steel	
				0
HS-AS10	Quick Fit Male	M12 Male		
HS-AS12	Quick Fit Male	1/4"NPT Male		





