



What's in the box?




1. Configure




Default configuration

(Quality warning thresholds are configurable)



NOTE Please complete and return survey

2. Install and connect



NOTE: Ensure sensor configured correctly - refer to sensor manual

3. Activation steps

- Check installation
- Power On
- Wait for 1 minute
- Check output

4. Bluetooth (optional)

Download App, connect to OQDe



Troubleshooting

1. Check configuration (step 1)
2. Refer to manual
3. www.tandeltasystems.com
4. support@tandeltasystems.com

Tan Delta System Architecture

